

Product Brochure For L183

Centre Lathe - AL-335

300 x 910mm Turning Capacity
Includes Cabinet Stand



ORDER CODE:	L183
MODEL:	AL-335
Swing Over Bed (mm):	300
Distance Between Centres (mm):	910
Spindle Bore (mm):	38
Swing In Gap (mm):	450
Swing Over Cross-slide (mm):	178
Digital Readout System Fitted:	Optional
Quick Change Toolpost Fitted:	Optional
Leadscrew Covers Fitted:	~
Taper Turning Attachment:	~
Coolant System:	~
Tool Height To Suit (mm):	12
Centre Height (mm):	150
Spindle Nose Size or Type:	D1-4 Camlock
Bed Width (mm):	180
Headstock Spindle Taper (MT):	5
Tailstock Taper (MT):	3
Cross Slide Travel (mm):	170
Compound Slide Travel (mm):	76
Leadscrew Type:	Imperial
Metric Cross Feed (X-Axis) (mm/rev):	~
Imperial Cross Feed (X-Axis) (inch/rev):	0.014 - 0.344
Metric Longitudinal Feed (Z-Axis) (mm/rev):	~
Imperial Longitudinal Feed (Z-Axis) (inch/rev):	0.05 - 1.29
Metric Thread Steps & Pitch (No. / mm):	36 (0.4 - 7)
Imperial Thread Steps & TPI (No. / TPI):	36 (4 - 60)
3 Jaw Chuck Diameter (mm):	160
4 Jaw Chuck Diameter (mm):	200
Spindle Steps / Speeds (No. / rpm):	9 (75 - 1400)
Motor Power (kW / hp):	1.5 / 2
Voltage / Amperage (V / amp):	240 / 10
Nett Weight (kg):	460

Description

A high quality specification, floor standing, heavy duty metal turning lathe suitable for the enthusiastic home model engineer, general maintenance and small work shops. Featuring a precision ground, induction hardened bed, fully gear driven spindle with hardened and ground gears with a speed range of 75 - 1400rpm, selectable via the front of headstock mounted gear selection levers.

2hp single phase 240 volt motor is supplied on machine, taper roller spindle bearings, range of cross and longitudinal feed speeds selected on a separate gearbox, thread chasing dial, chuck guard with safety interlock, splash guard and work lamp.

Supplied with a large range of standard accessories including a 150mm(6") 3 jaw self centring chuck, 200mm(8") 4 jaw independent chuck, face plate and dead centres. 5 to 3 MT reduction sleeve, steady rest, follow rest, standard tool post, floor stand with a swarf tray. Change gears and toolbox with maintenance tools.

Features

- Gear driven headstock for quick change of spindle speeds
- Precision V-beds are induction hardened and ground, incorporated with rigid webbed castings
- Low voltage halogen work light
- Change gears for metric and imperial thread cutting
- Adjustable taper roller bearings support the spindle
- 9 spindle speeds from 75 to 1400rpm
- Saddle hand wheel mounted on right side of apron reducing swarf contacting the hand
- Inching button is incorporated on the control panel for convenient spindle speed selection
- Quick-action gearbox for thread cutting and auto feeding

Product Brochure For L183

- D1-4 camlock spindle for quick and accurate chuck removal and safe reverse direction turning. ISO standard
- External adjustable cross feed lead-screw nut
- Powered longitudinal and cross feeds
- Bed wipers on saddle
- Removable gap bed-way for larger diameter jobs
- Dual calibrated dials (except for saddle hand-wheel)
- Chuck guard fitted with safety micro switch
- Chuck & change gear guards are fitted with micro switches

Includes

- 3-jaw chuck with reverse jaws
- 4-jaw chuck
- Face plate
- Fixed steady
- Travelling steady
- Change gears
- Dead centre
- Thread-chasing dial
- Rear splash guard & swarf tray
- Safety chuck guard
- Cabinet stand
- Spanners
- Tool box
- Instruction booklet

Specific Features



Headstock



Speed Levers

CAUTION NO CHANGE OF LEVER WHEN GEARS AND SHAFTS ARE RUNNING			
SPINDLE	SPEEDS		
	1	2	3
A	270	1400	840
B	75	380	220
C	200	1050	640

POWER

Spindle Speed Chart



Switches



Feed and Thread Gearbox

		/mm							
position		E2	E3	E4	B2	B3	C3	C4	A1
48T	SI	1.291	1.107	0.996	0.922	0.830	0.738	0.711	0.632
100T	SI	0.331	0.283	0.256	0.236	0.212	0.190	0.182	0.162
24T	SI	0.646	0.553	0.498	0.461	0.415	0.369	0.356	0.316
	SI	0.166	0.142	0.128	0.118	0.106	0.095	0.091	0.081
24T	SI	0.323	0.277	0.249	0.230	0.208	0.184	0.178	0.158
120T	SI	0.083	0.071	0.064	0.059	0.053	0.047	0.046	0.041
48T	SI	0.161	0.138	0.125	0.115	0.104	0.092	0.089	0.079
	SI	0.041	0.035	0.032	0.030	0.027	0.024	0.023	0.020

Metric Feed Chart

		/inch							
position		E2	E3	E4	B2	B3	C3	C4	A1
48T	SI	0.054	0.046	0.042	0.038	0.035	0.031	0.030	0.026
	SI	0.014	0.013	0.011	0.010	0.009	0.008	0.008	0.007
24T	SI	0.027	0.023	0.021	0.019	0.017	0.015	0.015	0.013
	SI	0.007	0.006	0.006	0.005	0.005	0.004	0.004	0.003
24T	SI	0.013	0.012	0.010	0.010	0.009	0.008	0.007	0.007
	SI	0.003	0.003	0.003	0.003	0.003	0.002	0.002	0.002
48T	SI	0.006	0.006	0.005	0.005	0.004	0.004	0.004	0.003
	SI	0.002	0.002	0.002	0.001	0.001	0.001	0.001	0.001

Imperial Feed Chart

		THREADS METRIC PITCHES mm									
position		D4	C4	C3	C2	A4	B2	E4	A2	E2	
48T	MI	0.4	0.45	0.5	0.5625	0.6	0.625	0.7	0.75	0.875	
	MII	0.8	0.9	1	1.125	1.2	1.25	1.4	1.5	1.75	
24T	MI	1.6	1.8	2	2.25	2.4	2.5	2.8	3	3.5	
	MII	3.2	3.6	4	4.5	4.8	5	5.6	6	7	

		THREADS IMPERIAL PITCHES 1/inch							
position		A2	A3	C3	A4	C3	C3	A1	D4
48T	Z	24	24	38	24	22	24	26	24
	MII	4	4½	9½	5	5½	6	6½	7
24T	Z	8	9	19	10	11	12	13	14
	MI	16	18	19	20	22	24	26	28
	MII	32	36	38	40	44	48	52	56

Metric and Imperial Thread Charts

Product Brochure For L183


INDICATOR TABLE					
1/4 inch	4	4 1/2	5	6	7
SCALE	1-8	1	1*5	1*3*5*7	1*5
1/2 inch	8	9	10	11	12
SCALE		1*5	1*3*5*7	1*5	1-8
3/4 inch	13	14	15	16	18
SCALE	1*5	1*3*5*7	1*5	1*3*5*7	1*3*5*7
1 inch	19	20	22	24	28
SCALE	1*5	1-8	1*3*5*7		1*3*5*7

CAUTION


Indicator Table



Chuck Guard




3 Point Steady




2 Point Steady




Halogen Light




Saddle



Saddle Left View




Toolpost




Compound Slide



Thread Chasing Dial




Forward Reverse Spindle Lever




Feed Engagement Lever



Compound Slide Hand Wheel



Cross Feed Handle



Saddle Hand Wheel




Tailstock


Product Brochure For L183



Tailstock Quill



Tailstock Handle



Induction Hardened Bedways

Recommended Accessories

G660
Lathe Leadscrew Cover Kit



G659
Lathe Leadscrew Cover Kit - Concertina



L300
Magnetic Swarf Remover



M9991
Magnetic Floor Sweeper



L0099
Lathe Turning Tool Kit - 7 piece Insert Type



L0098
Carbide Inserts - General Purpose



L450
Lathe Turning Tool Kit - 3 piece Insert Type



L456
Lathe Threading Tool Kit - Insert Type



Product Brochure For L183

L464

Professional Lathe Parting Tool Kit - Insert Type



L074

Parting Tool Holder - Suits 1/2" HSS Tool Bit



L0007

Part Off Blade - High Speed Steel Bit



C052

3MT Live Centre



C290

Heavy Duty Drill Chuck - Keyed Type



D443A

3MT x JT3 Drill Chuck Arbor



L076

Knurling Tool Holder Kit



P235

Coolant Pump & Tank



L295

Quick Change Toolpost




L295A

Quick Change Toolpost Holder - Std



L341

Fitting and Machining Technical Book




L345

Handy Workshop Tips & Techniques - 1st Edition



Product Brochure For L183

L3455
Professional Sheet Metal Fabrication Book



D1272
Metric 135° Precision HSS Drill Set - 25 Piece



D1282
Imperial 135° Precision HSS Drill Set - 29 Piece



D126
Metric 135° Precision HSS Drill Set - 170 Pieces



L277
Vertical Mill Slide



D720C
200mm Easson Digital Readout Scale



D734
900mm Easson Digital Readout Scale




C980
5C Collet Lathe Adaptor



M800
Rubber Mat - Anti-Fatigue



M805
Rubber Mat - Anti-Fatigue



S090A
Soluble Metal Cutting Fluid - 1 Litre



S090
Soluble Metal Cutting Fluid - 5 Litre



Product Brochure For L183

S076

Cutting Tool Lubricant Fluid - 500ml



S077

Drilling, Tapping & Cutting Tool Lubricant Spray - 400g



S074

Cutting Tool Lubricant Paste - 500g



O043

Rust & Corrosion Preventive



O042

General Purpose Lubricant & Corrosion Inhibitor



O044

Rust & Corrosion Preventive

